

## Architect's Field Report

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	20 June 2020  18059-AOI Academy of Innovation / Report Number 039
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Contract Century Construction Date / Time 18 June 2020 / 11:00 AM Weather / Temp Clear / 85 ° F Est % Complete 60% Sched Conformance + 68 days Work in Progress Structural Steel Install Interior Framing Mechanical Install
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Present at Site Joey Moore, Century Construction Will Commarato, DBA Paul Purser, DBA  Observations Arriving on site, I met Joey Moore, CC who was just discussing an offset of structural steel in a column line at the North Structure with Will Commarato, DBA. This offset was deemed acceptable.  I walked the interior with Mr. Commarato afterwards. We reviewed framing throughout but specifically at the upper furr down curve in the Main Lobby on the south side of the central structure. The curve is close but still needs some adjusting.  We also discovered an erosion issue at the West Elevation of the North Structure that needs attention before the next rain.
	Items to Verify None Action Required None Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Will Commarato / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Jerry Montgomery (SM)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – East Structure



Figure 2 – East Structure Framing





Figure 3 – Blocking in East Structure Ongoing



Figure 4 –Interior Framing Ongoing





Figure 5 – Furr Down Curve Needs Attention



Figure 6 – Furr Down Curve Needs Attention (adjusting required at straightened portion)





Figure 7 – Multi Purpose 230



Figure 8 – Lobby 250, Corridor 251





Figure 9 – Versatile Teaching 220



Figure 10 – 2<sup>nd</sup> Level Stair at West Structure





Figure 11 – Unsightly Weld at stair to structure (Assuming this is temporary)



Figure 12 – West Elevation at North Structure Erosion





Figure 13 – West Elevation at North Structure



Figure 14 – Secondary Structural Wall Installed Between Central and East Structures





Figure 15 – Structural Steel Welding @ East Façade of North Structure



Figure 16 – Structural Steel Welding @ East Façade of North Structure